



Photo 1 – Completion of Lateral Geothermal Piping Installation in field #1.



Photo 2 – Geothermal Well Drilling in Field #3.



Photo 3 – Pouring Level 5 Building A Slab.



Photo 4 – Final Slab on Deck for Building B Roof.





Photo 5 – Erecting Steel in Building C/D.



Photo 6 – Topping-off Steel Erection.



Photo 7 – Iron Workers Adjust Lintels in Building A.



Photo 8 – Area A Underground Utilities Completed.





Photo 9 – Area A Spray Fireproofing on Structural Steel.



Photo 10 – Area A Radiant Piping and Spray Fireproofing.