



Photo 1 – Geothermal Well Drilling in Field #3.



Photo 2 – Geothermal Well Drilling in Field #3.



Photo 3 – Area C Radiant Piping Prior to Slab on Deck Placement.



Photo 4 –Slab on Deck Placement for Building C/D Level 2.



Photo 5 – Building A Corridor with MEP components, wall framing, and some sheathing installed.



Photo 6 – 1st-in-Place Inspection of Sheathing with Gary Hewitt (SKA) and Jeff Brussel (PW).



Photo 7 – Building A West Elevation Being Framed.



Photo 8 – Building A East Elevation External Sheathing.



Photo 9 – Floor Protected Field House with Chairs Located to Accommodate Socially Distanced Meetings.



Photo 10 – Griffin Electric Working in Field House.