


Progress Photos

- Area B, South façade – multi-story curtain wall




Progress Photos

- Area C, level 1 – main mechanical room equipment



- Area B, level 2 – sound isolating GWB ceiling soffit



Progress Photos

- Area B, North façade – clearstory windows and masonry under weather protection



Area C, level 2 – scaffold staging for pool ceiling




Progress Photos

- Area B, North façade – glazing, metal panels and masonry



Progress Photos

- Area B, level 3 – Stair #13 steel at auditorium stage



- Area C, level 3 – Stair #3 steel and concrete



Progress Photos

- Area A, West façade – glass, metal panels and sunshades



- Area B, level 2 – intumescent paint for structural columns, drywall, and multi-story curtain wall

