



Photo 1 – Reinforcing Pile Caps and Grade Beams in Area C.



Photo 2 – Forming Pile Caps and Grade Beams in Area C.



Photo 3 – Concrete Placement in Area A.



Photo 4 – Concrete Progress in Area A.





Photo 5 – Progress of Drainage Piping Installation.



Photo 6 – Progress of Drainage Installation at South Side of A Wing.



Photo 7 – Structural Steel Install in Auditorium.



Photo 8 – Structural Steel Installation.





Photo 9 – Geothermal Piping Coils, Grout and Drill Rig.



Photo 10 – Geothermal Frac-Tank.