



Photo 1 – Commencement of Lateral Geothermal Piping Installation.



Photo 2 – Geothermal Well Drilling in Field #2..



Photo 3 – Finishing Level 3 Building B Slab.



Photo 4 – Finishing Level 2 Building A Slab.



Photo 5 – Radiant Tubing Installed Within Slab on Metal Deck.



Photo 6 – Erecting Steel in Building C/D.



Photo 7 – Building A and B Erection Completed.



Photo 8 – Under-slab Utility Work in Building A.




Photo 9 – MEP/FP Coordination Model
Snap Shot.



Photo 10 – COVID-19 Face Covering PPE Signage.



Photo 11 – Workers with Face Covering PPE.



Photo 12 – Hand Wash Station Map Signage.



Photo 13 – Trades Using Permanent Hand Wash Stations.