



Photo 1 – Geothermal Well Drilling in Field #3.



Photo 2 – Installation of Lateral Piping in Field #2.



Photo 3 – Area A Slab on Grade Rebar Installed to Receive Pour.



Photo 4 – Slab on Grade Placement for Building A Level 1.



Photo 5 – Building A Corridor with MEP components, wall framing, and some sheathing installed.



Photo 6 – Select Spray Applying Spray Fireproofing to Auditorium Area in Building B.



Photo 7 – Building A West Elevation Being Sheathed.



Photo 8.1 & 8.2 – Detailed and Sprayed AVB in Building A.



Photo 9 – Plumbers Install Roof Drains; Pipe-Fitters Install Fire Protection Piping.



Photo 10 – South Side of Gym Showing Blocks installed by Commercial Masonry and Overhead MEPs .