

Photo 1 – Start of Construction of Permanent Roads.



Photo 2 – Site Overview from Skanska Trailers.






Photo 3 – Auditorium Rebar and Mesh in Place for Upcoming Slab on Deck Pours.

Photo 4 – Area B Slab on Grade Rebar Installed to Receive Pour (Electrical Room Area).






Photo 5 – Building B Stair #2 Being Installed.

Photo 6 – Insulation and Sheathing Installation on Low Roof of Building B.





Photo 7 – Brick Installation at Building A East and Sheathing Installation at Building C South. Photo 8 – Building B with Classroom Window Frames/Temporary Plywood Installed.






Photo 9 – Spray-Foam Insulation Installed at Building C, Level 5 Skylight. Photo 10 – Two Masons Install Bricks at Building A East Elevation.