

Progress Photos

- Photo 1: Under-slab duct for pool drain ventilation




- Photo 2: Installation of vapor barrier and rebar in preparation of pouring slab on grade in area C




Progress Photos

- Photo 3: First slab on grade pour of area C



- Photo 4: Installation of multi-story curtain wall at Area C South



Progress Photos

- Photo 5: Northwest elevation of Area B during installation of masonry and windows
- Photo 6: Installation of brick ties at south elevation of B Building



Progress Photos

- Photo 7: Installation of masonry at west elevation of A building



Progress Photos

- Photo 8: Setting HVAC rooftop units in area C mechanical well



- Photo 9: Area A, Level 2 interior finish ready for paint

