



Progress Photos

- Area C Level 1: Mechanical Rm, formwork for housekeeping pads



- Area C Level 3: Maker's Space application of intumescent paint



Progress Photos

- Area C Level 1: installation of CMU wall at pool




- Area C Level 1: framing at pool locker rooms



Progress Photos

- Area A Level 2: installation of rubber floor in classroom




- Area B Level 4: movable partition track and ceiling grid



Progress Photos

- Area A East Façade: masonry, windows, and metal panels



- Area A Level 3: corridor tile with protection



Progress Photos

- Area B Level 1: Band Rm drywall and tape



- Area B Level 3: Auditorium Catwalk

