

Progress Photos

- Installation of retaining wall East of Football/Rugby Field




Progress Photos

- Installation of retaining wall with geothermal vault tie-in




- Installation of carpet in Media Center



Progress Photos

- Installation of casework in administration area
- Installation of Armstrong acoustic drywall ceiling (ACT-14)



Progress Photos

- Area C Café Commons




Progress Photos

- Middle School Band Room K-13 acoustical spray and lighting



Progress Photos

- Installation of floor tile in Area C Café Commons



Progress Photos

- Area A typical office





- Administration break room



Progress Photos

- Installation of tiered seating structure in Auditorium



Progress Photos

- Field House renovation – new electrical infrastructure and misc. metals supports for new fitness center on mezzanine

