

Progress Photos

- ACT-14 ceiling at Stair 3




- Installation of lockers



Progress Photos

- Installation of drainage around Rugby Field




Progress Photos

– Installation Mezzanine structure in Field House



Progress Photos

- Area A, 1st Floor, administration area finishes



Progress Photos

- Area B Corridor finishes



- Area C Corridor wood veneer panels




Progress Photos – High School Main Entrance metal panel installation



Progress Photos

– Auditorium tiered seating installation



Progress Photos

– Installation of grating in Area C Mechanical Well



Progress Photos

– Sidewalk installation

